EAGLE SERVICE™ PLAN

PT6A-34 ESP® PROGRAM

Pay-per-hour engine service plan providing

- Guaranteed long-term engine maintenance cost
- · Accurate budgeting, forecasting, and smooth cash flow
- Enhanced aircraft resale value

The ESP® Program

- Is transferrable to the next operator globally
- Has no management fees or enrollment fees
- Has no minimum annual utilization requirement



Offered by the designer and manufacturer of your P&WC engines

Backed by P&WC's facilities, parts, rental engines, and technical experts

More than just a trust fund or financial institution

www.pwc.ca/esp ← CLICK HERE

4 LEVELS OF COVERAGE **

	SILVER LITE	SILVER	GOLD LITE	GOLD
Overhaul / Refurbishment, scheduled	0			<u> </u>
Engine repair, basic unscheduled (BUER)				
HSI - Scheduled or required				
Service bulletins, required				
Engine shop labour				
Troubleshooting labour				<u> </u>
Engine parts (excluding Life Limited Parts)				
Engine accessories, P&WC supplied				
Rental / lease engine coverage (overhaul / BUER)				<u> </u>
Engine Condition Trend Monitoring (ECTM®) analysis				
Life Limited Parts				
Line removal / installation / access labour				
Freight for engine, engine parts, accessories				
Mobile Repair Team for unscheduled AOG				

^{**} Some exclusions apply, such as scheduled routine maintenance (labour, o-rings, gaskets, oil, filters, etc) and environmental factors. For further details, consult with your P&WC representative.

2014 ESP® PROGRAM HOURLY RATES (U.S.\$) (1) PT6A-34

	SILVER LITE		SILVER		GOLD LITE		GOLD	
Cycles Per Hour / Mission Length	Basic	Early Enrollment ⁽²⁾	Basic	Early Enrollment ⁽²⁾	Basic	Early Enrollment ⁽²⁾	Basic	Early Enrollment ⁽²⁾
0.10 TO 1.00 > 60 Minute Flights	\$106.30	\$95.65	\$119.00	\$107.10	\$115.85	\$104.25	\$128.45	\$115.60

⁽¹⁾ Rates are per engine, per hour, U.S. dollars, excluding any applicable taxes. Rates subject to annual adjustment.

Above rates applicable to operations with an average flight cycle of 60 minutes or greater, based on a 6 month rolling average

P&WC Proprietary and Controlled Information

For more information on enrollment, please contact:

ESP® Program Administration

Tel: +1 (450) 468-3771 or +1 (888)-479-2377; Fax: +1 (450) 647-9652

Email: esp.admin@pwc.ca Website: www.pwc.ca/esp

Subject to change without notice. December 2013

EXPORT CONTROL CLASSIFICATION
This document does not contain technical data



⁽²⁾ Early Enrollment rate available when enrolling with less than 200 hours TTSN. Early Enrollment rate applicable up to 2,000 hours TTSN.